DART SERVICE BULLETIN SB18-3

REF. TCCA STC: SH93-4 REF. FAA STC: SR00028NY/SR00029NY REF. EASA STC: 10016984 REF. ARGENTINA STC: CTS-0508.13(A) REF. RUSSIA TC: CT107-350

1.0 PURPOSE

It has come to Dart's attention that the D350-578-015/-017/-115/-117 Bearpaw Installations could prevent the D2741 Blade that is installed on Dart D350-636-XXX Skidtube with Training Wearplates from contacting the ground and performing its intended function.

2.0 ACTION

The DSI 9812-011 Shim Kit should be installed per DSI 9812 when the D350-578-015/-017/-115/-117 Bearpaws are installed on Dart D350-636-XXX Skidtubes with Training Weaplates.

These documents may be obtained from DART's website (www.dartaerospace.com).

For further information, contact DART Aerospace at:

DART AEROSPACE LTD. 1270 Aberdeen Street Hawkesbury, ON, K6A 1K7 Canada

Tel: 1 613 632 5200 Fax: 1 613 632 5246

email: support.on@dartaero.com website: www.dartaerospace.com

Α	NEW IS	ISSUE RF			18.10.31
REV.		DESCRIPTION BY			DATE
DESIGN		RF	DART AEROSPACE LTD		TD
DRAWN		RF	HAWKESBURY, ONTARIO, CANADA		
CHECKED		VS	DRAWING NO.		REV. A
MFG. APPR.		N/A	SB18-3		SHEET 1 OF 1
APPROVED		VS 🦼	TITLE		SCALE
DE APPR.		DŜ	SERVICE BULLETIN		NTS
DATE 18.10.31			COPYRIGHT © 2018 BY DART AEROSPACE LTD. THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPED OR COMMANINICATE TO ANY DITERS PRISON WITHOUT		

WRITTEN PERMISSION FROM DART AEROSPACE LTD.